



Parts Update kit Armstrong Cab handrail holes

An error has come to light re the position of the cab handrail effecting parts 096 and brass overlay B003.

The overlay should be assembled to 096 prior to drilling.

Please see the illustration below for positional details.

